

HABS  
ID  
11- EAPO.  
1-

## **HISTORIC AMERICAN BUILDINGS SURVEY**

### **INDEX TO PHOTOGRAPHS**

**United States Border Inspection Station  
West Side of U.S. Route 95  
Eastport  
Boundary County  
Idaho**

**HABS No. ID-101**

**Harvey S. Rice, Photographer June 1988**

**United States Border Inspection Station (ID-101)**

#### **EXTERIOR PHOTOGRAPHS**

- ID-101-1      CONTEXTUAL VIEW OF INSPECTION STATION AND RESIDENCES FACING ONTO  
STATE ROUTE 95, VIEW TO SOUTHWEST
- ID-101-2      CONTEXTUAL VIEW OF INSPECTION STATION, WITH KINGSGATE CANADIAN  
CUSTOMS STATION (CENTER BACKGROUND) AND EASTPORT COMMERCIAL  
BUILDINGS (RIGHT, ACROSS STATE ROUTE 95), VIEW TO NORTH
- ID-101-3      CONTEXTUAL VIEW OF REAR OF INSPECTION STATION AND RESIDENCES, WITH  
COMMUNICATIONS TOWER AND PUMPHOUSE (LEFT FOREGROUND), VIEW TO  
SOUTHEAST
- ID-101-4      INSPECTION STATION FACADE, VIEW TO NORTHWEST
- ID-101-5      INSPECTION STATION REAR ELEVATION, VIEW TO NORTHEAST
- ID-101-6      TWO-STORY CENTRAL MASS OF INSPECTION STATION, SHOWING UNALTERED  
REAR ELEVATION, VIEW TO SOUTHEAST

#### **INTERIOR PHOTOGRAPHS**

- ID-101-7      U.S. CUSTOMS OFFICE IN INSPECTION STATION, VIEW TO SOUTH
- ID-101-8      DETENTION CELLS, SECOND FLOOR OF INSPECTION STATION, VIEW TO SOUTH
- ID-101-9      STAIRS AND REAR DOOR OF INSPECTION STATION, FIRST FLOOR, VIEW TO WEST
- ID-101-10     STAIRS IN INSPECTION STATION, VIEW FROM SECOND FLOOR LANDING

(continued)

UNITED STATES BORDER INSPECTION STATION  
HABS NO. ID-101  
INDEX TO PHOTOGRAPHS (Page 2)

ID-101-11 INSPECTION PIT IN SOUTHERNMOST BAY OF CUSTOMS GARAGE (SOUTH WING OF INSPECTION STATION), VIEW TO WEST

HISTORIC VIEWS (FROM THE GENERAL SERVICES ADMINISTRATION, AUBURN, WASHINGTON)

ID-101-12 Photocopy of a photograph of the Inspection Station before major alteration  
Photographer unknown, July 1957  
VIEW TO THE NORTHWEST

ID-101-13 Photocopy of a photograph of the Inspection Station before major alteration  
Photographer unknown, July 1957  
VIEW TO THE SOUTHWEST

ORIGINAL DRAWINGS (FROM THE GENERAL SERVICES ADMINISTRATION, AUBURN, WASHINGTON)

Note: Photograph Nos. ID-101-14 through ID-101-21, and ID-101-A-6 and ID-101-A-7 are 8" x 10" enlargements from 4" x 5" negatives.

ID-101-14 Photocopy of an original drawing  
28 March 1935  
SURVEY OF INSPECTION STATION SITE

ID-101-15 Photocopy of an original drawing  
17 June 1935  
APPROACH PLAN (SITE PLAN)

ID-101-16 Photocopy of an original drawing  
24 May 1963  
PLANTING PLAN & MISC. REPAIRS & DETAILS (LANDSCAPING; DETAILS OF FENCES, RETAINING WALL, OUTDOOR STAIRS)

ID-101-17 Photocopy of an original drawing  
3 May 1935  
INSPECTION STATION ELEVATIONS

ID-101-18 Photocopy of an original drawing  
3 May 1935  
INSPECTION STATION FLOOR PLANS, BASEMENT AND SECOND FLOOR, END ELEVATIONS AND CROSS SECTIONS, CANOPY AND ROOF DETAILS

ID-101-19 Photocopy of an original drawing  
3 May 1935  
INSPECTION STATION FLOOR PLANS, FIRST FLOOR, DRIVEWAY DETAILS

(continued)

UNITED STATES BORDER INSPECTION STATION

HABS NO. ID-101

INDEX TO PHOTOGRAPHS (Page 3)

- ID-101-20      Photocopy of an original drawing  
8 March 1971  
INSPECTION STATION ALTERATIONS, FACADE, INTERIORS, AND CANOPY
- ID-101-21      Photocopy of an original drawing  
29 March 1979  
INSPECTION STATION, HANDICAPPED AND MINOR ALTERATIONS (DETAILS OF  
TOILETS IN SOUTH WING)